

**Customer:** NSM

**Location:** Birmingham, AL

**Time & Duration:** 8 Weeks

**Technical Description:** Robot Programming

Reference: NSM 13-284 / 1.1.1



## Problem

Robots used in a tandem press to advance metal parts, so each press can accurately and quickly stamp parts.

## Solution

Teach and optimize robots

## INP Tasks

- Big issue (Siemens) Profinet safety I/O's communication between PLC's and resets troubleshoot Profinet DCS safety.
- Check safety I/O's at robot.
- Confirmed setup of robot is ok.
- Detected error in the setup or safety PLC.
- Received information from press OEM that robot configured correctly.

## Checked:

- Safety PLC logic at the PLC and the PROFIsafe configuration at the robots.
- Profinet communication at R4, R5 and R6.
- The I/O configuration at R2, R3, R4, R5 and R6.
- The interface configuration between R1 and WIA

## Test:

- Add a new I/O for the robot.
- Testing the full auto mode at R1 and destacker.
- Include 4 sensors at the 2 tooling stands to the robot program

### MEXICO

INP Mexico S.A de C.V  
Fray Junipero Serra #2450  
Suite 501  
Pabellón Cooperativo Juriquilla  
76230 Queretaro  
Mexico

Tel. +52 442 3930703  
mx.inp@actemium.com

### USA

INP North America Inc.  
11390 Old Roswell Rd.  
Suite 126  
Alpharetta, GA 30009  
USA

Tel. +1 678 527-1400  
Fax +1 678 527-1410  
us.inp@actemium.com

### CANADA

INP Canada Inc.  
2275 Upper Middle Rd E  
Suite 101  
Oakville, Ontario L6H 0C3  
Canada

Tel. +1 678 527-1400  
ca.inp@actemium.com